

BONDERITE®

Touch-N-Prep® pens are designed for easy and safe repair of clean, bare, or previously painted aluminum surfaces. Tips can be replaced following these steps:



Step 1: Remove the cap.




Step 2: Remove the existing tip.



Step 3: Insert replacement tip.



Step 4: Holding the Touch-N-Prep® pen upright, press and hold the pen tip down on the surface.




Step 5: Apply BONDERITE® pen solution to the aluminum surface.



Step 6: Discard the replacement tip after use and cap the Touch-N-Prep®.



BONDERITE®



Touch-N-Prep® pens are designed for easy and safe repair of clean, bare, or previously painted aluminum surfaces. Tips can be replaced following these steps:



Step 1: Remove the cap.



Step 2: Remove the existing tip.



Step 3: Insert replacement tip.



Step 4: Holding the Touch-N-Prep® pen upright, press and hold the pen tip down on the surface.



Step 5: Apply BONDERITE® pen solution to the aluminum surface.



Step 6: Discard the replacement tip after use and cap the Touch-N-Prep®.

Henkel